# **Formulate Essential Straight Banner**

#### FMLT-ESS-S-1000-2

The Formulate® Essential Banner 1000 - Straight measures 39.5"W, 92"H and features a simple straight bungee-corded tube frame and a fabric graphic that simply slips over the frame. Perfect for any environment - from retail to trade show!





We are continually improving and modifying our product range and reserve the right to vary the specifications without prior notice. All dimensions and weights quoted are approximate and we accept no responsibility for variance. E&OE. See Graphic Templates for graphic bleed specifications.

#### features and benefits:


- Straight bungee-corded aluminum tube frame with rounded corners
- Slip-over fabric graphic
- Easy to store and ship
- Quick to set up


- Kit includes: frame, dye-sublimated graphic, two feet
- Carry bag included
- One year hardware warranty against manufacturer defects

#### dimensions:


Hardware	Graphic
Assembled unit: 40.9"W x 93"H x 15"D 1039mm(w) x 2363mm(h) x 381mm(d)	Refer to related graphic template for more information.
Approximate weight:	One year warranty.
6 lbs / 3 kg	Visit: www.exhibitors-handbook.com/ graphic-templates
Shipping	additional information:
Packing case(s): 1 Box(es)	Graphic material: Dye-sublimation pillowcase fabric
Shipping dimensions: 33"l x 11"h x 3"d 839mm(l) x 280mm(h) x 77mm(d)	When included in a larger kit, a different packaging solution will be listed to accommodate all contents of the kit. Individual packaging no longer provided.
Approximate total shipping weight: 7 lbs / 4 kg	
	1 person assembly recommended:

# **Included In Your Kit**






# **Exploded Diagram**



# **Labeling Diagram**

FMLT-ESS-S-1000-2



# **Kit Assembly**


## **Step by Step**

## Step 1.

Gather the components to build the frame. Use the Exploded View and the Labeling Diagram for part labels.

Reference Connection Method(s) 1 for more details.





## Step 2.

Gather the components to attach base hardware. Use the Exploded View and the Labeling Diagram for part labels.

Reference Connection Method(s) 2 for more details.





## Step 3.


Gather the components to attach the graphic. Use the Exploded View and the Labeling Diagram for part labels.





Step 4.


Setup is complete.



## **Connection Methods**

#### Connection Method 1: FMLT-ESS-S-FOOT -

### -Connection Method 2: Swage Tube with Snap Button-



the set screw to hold the insert in place.

First, attach the base plate with the M10 screw. Once the base plate is in the desired position, fasten Attaching the tube swage design end and snap button is easy - simply press the snap button in and slide it into the next tube. With the tube on, make sure the snap button comes out all the way through the tube hole.